

PRODUCT BULLETIN:
EFLC1105A mCX
Extension Bulletin:




April 22, 2016

Product: mCX Battery Extension included with EFLC1105A Charger

Issue: The mCX battery extension is wired incorrectly. The leads have been wired in reverse polarity.

What To Do: If you are not using the extension, please dispose of it. If you need a replacement extension, contact Horizon Product Support.

This product, when used with the E-flite EFLC1105A charger, does not pose a safety concern. The charger will error out if you attempt to use the lead to charge a battery. Do not use this lead with any other product, as Horizon cannot guarantee how other brands' chargers will react with the lead.



Horizon disclaims all liability and warranties for any consumer who does not act upon this bulletin. We apologize for this inconvenience. If you have any questions, please call Horizon Hobby Product Support at 877-504-0233.

Contact Information

Country of Purchase	Horizon Hobby	Contact Information	Address
United States of America	Product Support	productsupport@horizonhobby.com 877-504-0233	4105 Fieldstone Rd Champaign, Illinois, 61822 USA
	Sales	sales@horizonhobby.com	
		888-959-2304	

If you purchased your product outside of US, please see the retailer or distributor you purchased your product from for assistance.